

## Under Review Notification

Raised By: Steven Drouin

Product #: D412-694

Date: 18.06.05

Product Name: Spacedoor

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
D412-694-011	IIN-D412-694 Rev. B	Y	Y	N	Y	Y	Y	Y	739	Change # 007
D412-694-115	IIN-D412-694 Rev. B	Y	Y	N	Y	Y	Y	Y	739	Change # 002
DSI 9462-011	DSI 9462 Rev A	Y	Y	N	Y	Y	Y	Y	739	Revise Drawing
DSI 9715	DSI 9715 Rev A	Y	Y	N	Y	Y	Y	Y	739	Revise Drawing

### Description of Issue:

Ref: CAR18-225

Seal D3237-1/-3 0980 length is too short, need to be changed to D3237-1-1030 and D3237-3-1030.

Comfirm with Engineering before making a W/O for D412-694-011/115

DSI 9715 should be removed from the bluefiles until issue is resolved.

### Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider